
PATENT



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
Mitsuya SATO) Examiner: K. Brown	n
Application No.: 09/472,993) Group Art Unit: 287	7
Filed: December 28, 1999	·)	
For: EXPOSURE APPARATUS AND EXPOSURE METHOD	:) August 24, 2005 :	
U.S. Patent No. 6,888,618 B2) :)	
Issued: May 3, 2005	Certification AUG 2 9 of Corre	icate
	AUG 2 9	2005
Commissioner for Patents	Of Corre	-4.
P.O. Box 1450	or corre	ction
Alexandria VA 22313.1450		

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

Attention: Certificate of Correction Branch

Patentee requests that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of U.S. Patent and Trademark Office mistakes and mistakes of a minor nature which are not the fault of the Patent and Trademark Office.

08/25/2005 JBALINAN 00000080 6888618 01 FC:1811 100.00 OP Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction. Any additional fee required by this paper may be charged to Deposit Account No. 06-1205.

Patentee's undersigned attorney may be reached in our Washington, D.C. Office by telephone at (202) 530-1010. All correspondence should continue to be directed to our below-listed address.

Respectfully submitted,

Attorney for Patentee

Steven E. Warner

Registration No. 33,326

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200
SEW/eab

DC_MAIN 212586v1

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.: 6,888,618 B2

: May 3, 2005 **DATED**

INVENTOR(S): Mitsuya SATO

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE COVER PAGE:

Under item "(*) Notice:" insert the following paragraph.

-- This patent issued on a continued prosecution application filed under 37 CFR 1.53(d), and is subject to the twenty year patent term provisions of 35 U.S.C. 154(a)(2). --

COLUMN 2:

Line 64, "FIG. 1" should read -- FIG. 1. --.

COLUMN 4:

Line 8, "It" should read -- If --. Line 58, "lamp 1" should read -- lamp 1. --Line 67, "a" should read -- an --.

COLUMN 7:

Line 5, "Idealistically," should read -- Ideally, --. Line 52, "memory" should read -- memory. --

MAILING ADDRESS OF SENDER:

PATENT NO. <u>6,888,618 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)

No. of add'l. copies @ 30¢ per page



Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.: 6,888,618 B2

DATED : May 3, 2005

INVENTOR(S): Mitsuya SATO Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 8:

Line 15, "can not" should read -- cannot --. Line 37, "lamp" should read -- lamp. --

COLUMN 9:

Line 5, "jobs." should read -- job. --.

COLUMN 10:

Line 11, "met" should read -- set --.

COLUMN 13:

Line 18, "it" should read -- if --.

COLUMN 15:

Line 6, "image" should read -- image. -- and "water" should read -- wafer --.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>6,888,618 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page



FORM PTO 1050 (REV. 3.82)